

## Service Bulletin

SUBJECT: GEM0956/MFI1256 COMPRESSOR

Number: 12-02 Product: Pearl/MFI Date Issued: March 2012

From: Technical Service

Due to manufacturing considerations, the compressor for the GEM0956/MFI1256 series has been changed. For GEM09565/MFI1256 <u>Versions 1 and 2</u> the original compressor is no longer available. The replacement kit includes: a new compressor, starting components, liquid line drier, compressor wiring harness, refrigeration tubing and adapters. This kit enables Versions 1 and 2 to use the new compressor.

Model Number	Prior to Serial Number	Part Number	<u>Description</u>
GEM0956 Air1&2, Water1&2, Remote1&2	12021280011341	1051187-01	Replacement Kit
MFI1256 Air1&2, Water1&2, Remote1&2	12021280011174	1051187-01	Replacement Kit

GEM0956/MFI1256 Version 3 will require the compressor only kit. (compressor, starting components and drier)

Model Number	From Serial Number	Part Number	<u>Description</u>
GEM0956 Air3, Water3 Remote3	12021280011342	9181145-11	Compressor only Kit
MFI1256 Air3, Water3 Remote3	12021280011175	9181145-11	Compressor only Kit

**Caution**: As with all compressor replacements, the system will require a cycle check and adjustment of product controls to allow the maximum capacity output for the customer.